

SITE PHOTOGRAPHS

Omeida Trading 406 cc Rectification of unlawful activities located on Holding 105 of Blue Hills Agricultural holdings under the jurisdiction of the City of Johannesburg Metropolitan Municipality, Gauteng Province




Figure 1: The Boundary Wall




Figure 2: Front section of the Boundary Wall




Figure 3: Corner section of the Boundary



Figure 4: Left section of the Boundary Wall



Figure 5: The Back Section of the Boundary Wall



Figure 6: The section where the Culvert is installed



Figure 7: The Culvert installed within the buffer of the Wetland




Figure 8: The Parking Area Boundary Wall




Figure 9: The Unfinished Attenuation dam



Figure 10: The Installed Culvert




Figure 11: The Installed Manhole




Figure 12: The Installed Manhole




Figure 13: The Installed Manhole



Figure 14: The Installed Manhole



Figure 15: The Installed Manhole




Figure 16: The unfinished Attenuation Dam



Figure 17: The Installed Boreholes



Figure 18: The Installed Boreholes



Figure 19: The Parking Area




Figure 20: The Parking Area